Standard Lead Times Matrix

SE ENCORE

SOLID OUTPUT SHAFT UNIT

Encore Size	Models	Assembly	Ratios	Motor Frame	Lead Time (business days)
E13 - E35	MDNS	ALL	5-100	56C - 140TC	5 Days
	MDTS	ALL	5-100	56C - 140TC	5 Days
	MDBS	ALL	5-100	56C - 140TC	5 Days
	MDVS	ALL	5-100	56C - 140TC	5 Days
	XDNS	ALL	5-100	56C - 140TC	5 Days
	XDTS	ALL	5-100	56C - 140TC	5 Days
	XDBS	ALL	5-100	56C - 140TC	5 Days
	XDVS	ALL	5-100	56C - 140TC	5 Days

HOLLOW OUTPUT SHAFT UNIT

Encore Size	Models	Assembly	Ratios	Motor Frame	Lead Time (business days)
E17 - E26	MDSS	DLR	5-100	56C - 140TC	5 Days
	MSTS	DLR	5-100	56C - 140TC	5 Days
	MSBS	DLR	5-100	56C - 140TC	5 Days
	MSFS	DLR	5-100	56C - 140TC	5 Days
	MSRS	DLR	5-100	56C - 140TC	5 Days

STAINLESS CONVEYOR DRIVE

Size	Models	Assembly	Ratios	Motor Frame	Lead Time (business days)
S17 – S30	MPMS	DLR	5-100	56C-140TC	5 Days
S17 – S30	MPSS	DLR	5-100	56C-140TC	5 Days

RD

Size	Models	Assembly	Ratios	Motor Frame	Lead Time (business days)
U13-U30	Solid Shaft	SR, SL	5-100	56C-140TC	5 Days
U18-U30	Hollow Shaft	All	5-100	56C-140TC	5 Days

ALUMINUM WORM

Size	Model	Assembly	Ratios	Motor Frame	Lead Time (business days)
030-085	ALRN	All	All	All	1-3 days
45 - 63	ALSQ	All	All	All	1-3 days

HELICAL GEARING

Size	Model	Assembly	Ratios	Motor Frame	Lead Time (business days)
412A- 613A	HXI	All	All	All	1-3 Days
X32S – X62A	HXB	All	All	All	1-3 Days